

Oil Field Environmental Incident Summary

Incident: 20150430090752 **Date/Time of Notice:** 04/30/2015 09:07

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: CEYNAR 4-18SWD

Field Name: TOBACCO GARDEN

Well File #: 90261

Date Incident: 4/29/2015 **Time Incident:** 18:30

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 99

Sec: 18

Qtr: LO T1

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels			3	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/27/2015

Clean Up Concluded: 4/30/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Contract salt water hauler has accepted full responsibility for the spill and all associated clean up.

Wastes Disposal Location: Contaminated soil to be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 4/30/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.